

---

**From:** Jeffrey C Heffelman (Generation - 3) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=JEFFRE3]  
**Sent:** 4/15/2015 5:01:04 AM  
**To:** Ed Baine (Generation - 3) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=Edwar62]  
**Subject:** Fwd: Ash Pond ABC inspection 04/14/15  
**Attachments:** 20150414123307440.pdf; ATT00001.htm

Sent from my iPhone

Begin forwarded message:

**From:** "Jeffrey R Marcell (Generation - 3)" <[jeffrey.r.marcell@dom.com](mailto:jeffrey.r.marcell@dom.com)>  
**Date:** April 14, 2015 at 12:34:58 PM EDT  
**To:** "Michael J Winters (Generation - 34)" <[Michael.J.Winters@dom.com](mailto:Michael.J.Winters@dom.com)>  
**Cc:** "John Cima (Generation - 34)" <[john.cima@dom.com](mailto:john.cima@dom.com)>, "Jeffrey C Heffelman (Generation - 3)" <[Jeffrey.C.Heffelman@dom.com](mailto:Jeffrey.C.Heffelman@dom.com)>, "Kenneth Roller (Services - 6)" <[kenneth.roller@dom.com](mailto:kenneth.roller@dom.com)>  
**Subject:** RE: Ash Pond ABC inspection 04/14/15  
Attached.

**Discharge** (seeping/flow into weir) at C Pond, about the same as previous inspection. Standing water around weir.

Standing water behind sand-bags at 'A' with standing water at the toe of the slope. The southern edge of the 'A' pond interior, from the SE corner to the sandbags, continues to hold water.

Current rainfall at time of inspection was 0.18".

Rain events 04/07 – 04/10 totaled 0.35".

Let me know if you have any questions.

Jeff Marcell  
Environmental Supervisor  
Possum Point Power Station  
Ladysmith & Remington CT Sites  
703-441-3813 (phone)  
8-795-3813 (tie)  
703-441-3897 (fax)